



Photography dated: 2020 Source: Esri, Maxar, Earthstar Geographics, and the GIS User Community
Although there is no reason to believe that there are any errors associated with the data used to generate
this product or in the product itself, users of these data are advised that errors in the data may be present.

Vauxhall Area Transmission Development - 879L Transmission Line Restoration Project

Existing Transmission Line

Existing 9 m Right-of-Way Boundary

-----Road

Crown Land











